

# BESSEY® Product Training



**BESSEY® Tools North America**  
**Metalworking: SC, BC and BCS Bearing Heaters**

# Metalworking: Bearing Heaters



Simply better.

## Why should a bearing be heated?

- ❑ When pressing (driving) a cold bearing onto a shaft more often than not the shaft will be damaged. The bearing itself may also be damaged during this process.
- ❑ RESULT: a bearing that is misaligned.
- ❑ Alignment issues can reduce a bearing's lifespan by 50%.
- ❑ Expansion of the bearing due to heating allows for **precise** placement and alignment of the bearing on the shaft **without** risking damage. NOTE: Normally a differential of 150 degrees F between the bearing and shaft will allow enough expansion for safe mounting.





# Metalworking: Bearing Heaters



Simply better.

## Heating by induction

- ❑ Electro-magnetic induction provides quick, even heating
- ❑ It is the superior method of heating a bearing.
- ❑ What is an “Induction Heater”?
- ❑ Basically a transformer with a short circuited secondary.
- ❑ In the base of the unit is a laminated steel core with a primary coil (winding). The laminated cross bar completes the core & the bearing becomes a short circuited, single turn, secondary coil.



# Metalworking: Bearing Heaters

## Hot Mounting General Instructions



- ❑ How Hot?
- ❑ Always follow the manufacturer recommendations for the bearing.
- ❑ Normally, do not heat a bearing to a temperature above 250 deg. F
- ❑ Do not heat bearings with seals or shields above 210 deg. F
- ❑ **Overheating** a bearing can cause changes in the metallurgical properties of the bearing steel, resulting in **premature failure!**
- ❑ Heat levels should be monitored constantly - a good device for this is a pyrometer. For your convenience BESSEY carries one, (Model: Pyrometer Kit)



# Metalworking: Bearing Heaters

## Hot Mounting General Instructions

- ❑ Clean protective gloves should be worn when mounting a bearing
  - Protection for the installers hands against heat.
  - Clean to prevent contamination of the bearing with destructive grit.
- ❑ Hoisting equipment can be used to help mount large bearings.
- ❑ To give some idea as to heating time requirements:
  - OD of 2" and width of 0.5" = Approximately 1 minute
  - OD of 4" and width of 1.0" = Approximately 2 minute
  - OD of 6" and width of 1.5" = Approximately 4 minute
  - OD of 8" and width of 2.0" = Approximately 8 minute



# Metalworking: Bearing Heaters

## Tips & Tricks


- ❑ Always use the largest cross bar that will fit through bearings hole.
- ❑ Bearings that are too large in diameter to be actually suspended from the cross bar can still be heated.
- ❑ Induction heating does not require direct contact. It is a heat generating process - not a heat transfer process.
- ❑ A large diameter bearing can sit on the base of the machine & the cross bar placed through the hole.
- ❑ Raising blocks are only required if the bearing race is thicker than the height of the posts, thus not allowing contact between the cross bar and both posts.
- ❑ Induction Bearing Heaters should not be placed on steel tables or carts. They should also be raised up about 18 inches from any heavily 'rebarred' concrete floor.
  - **WHY?** - Well because, the iron in the above mentioned items will “soak up” some of that heat inducing energy. Resulting in longer heating times.



# Metalworking: Bearing Heaters

## Models

- ❑ Model SC110D, Computer controlled, Single Phase
  - Bearing capacity: 4-3/8" x 11" OD, 14" OD with optional raising blocks
- ❑ Model SC110V, On/Off Switch, Single Phase
  - Bearing capacity: 4-3/8" x 11" OD, 14" OD with optional raising blocks
- ❑ Model BC, On/Off Switch, Single Phase
  - Bearing capacity: 8" x 22" OD, 32" OD with optional raising blocks
- ❑ Model BCS, On/Off Switch, Single Phase
  - Bearing capacity: 12-1/2" x 22" OD, 32" OD with optional raising blocks



**Reco induction bearing heaters**

| BESSEY®<br>Product # | Voltage      | Standard<br>Cross Bars | Optional<br>Cross Bars | Approx.<br>Weight<br>Pounds | Case |
|----------------------|--------------|------------------------|------------------------|-----------------------------|------|
|                      | Volts(amps)  | Inches                 | Inches                 |                             | qty. |
| SC 110D              | 110V(17 amp) | 3/4, 2                 | 1/2*, 1 1/4            | 56.00                       | 1    |
| SC 110V              | 110V(17 amp) | 3/4, 2                 | 1/2*, 1 1/4            | 52.00                       | 1    |
| SC 220V              | 220V(9 amp)  | 3/4, 2                 | 1/2*, 1 1/4            | 52.00                       | 1    |
| BC 220V              | 220V(30 amp) | 1 1/4, 3               | 3/4, 1, 2              | 200.00                      | 1    |
| BC 440V              | 440V(20 amp) | 1 1/4, 3               | 3/4, 1, 2              | 200.00                      | 1    |
| BC 550V              | 550V(20 amp) | 1 1/4, 3               | 3/4, 1, 2              | 200.00                      | 1    |
| BCS 220              | 220V(30 amp) | 1 1/4, 3               | 1", 2                  | 235.00                      | 1    |
| BCS 440              | 440V(20 amp) | 1 1/4, 3               | 1", 2                  | 235.00                      | 1    |
| BCS 550              | 550V(20 amp) | 1 1/4, 3               | 1", 2                  | 235.00                      | 1    |



# Thank you for your attention!

BESSEY® Tools North America